

## HOW TO GET METERS ON KYOCERA COPIERS

### **KM-650, 830, 1530, 2030, 2530, 3530, 4030, 4850 AND KM-C830D:**

There is a mechanical meter on right side of the machine (looks like the odometer in your car).

### **KM-3035, 4035 AND 5035:**

Hit the default settings/counter key on the top of the copier, then on the touch screen press counter check. There is a number under the word total-that is the meter to submit.

### **KM-C2030 AND KM-C3130:**

Go into utilities, hit meter count, there will be 2 print meters (1 black & white and 1 color) and there will be 2 copy meters (also 1 black & white and 1 color). Please make sure that you are submitting 4 separate meters.

### **KM-4500, 4530, 5500 AND 5530:**

Open the front door, there is a mechanical meter on top left corner.

### **KM-6230 AND KM-6330:**

Open the front door – there will be 2 mechanical meters; the correct meter will be the second set of numbers on the bottom.

### **FS-3800, 8000 AND 9500:**

Press the menu key, scroll down to life counters; hit the right arrow key, you should see a set of numbers, that is the meter we need. To go back just hit the menu key.

### **KM-1010, 1510 AND 1810:**

Press down the stop/reset key for approx. 5 seconds, it should flash f23 & then 2 sets of 3 numbers, write down all the numbers including zeros. Do not write down f23.

### **FS-C5016:**

Press the menu key, scroll down until you see print status page and enter twice, it will then print the page, please fax that to us along with the meter form we faxed you with your company information on it.

### **KM-1500:** hold down the clear key